

JON M. HUNTSMAN, JR. Governor

GARY HERBERT Lieutenant Governor

## Department of Environmental Quality

Richard W. Sprott Executive Director

DIVISION OF SOLID AND HAZARDOUS WASTE Dennis R. Downs *Director* 

October 29, 2008

Cole Peck Peck Rock & Products 1512 North 1300 East Lehi, Utah 84043

Subject: 2008 Inspection of Peck Rock Class VI Landfill

Dear Mr. Peck:

The Peck Rock Class VI Landfill was inspected on October 1, 2008 by Matt Sullivan of the Division of Solid and Hazardous Waste.

The landfill operations at the time of inspection were active with waste transporters frequently hauling in loads and disposing them at the base of the working face. The width of the working face spanned the clay pit end to end (about 75 yards), but it was controlled and managed by the heavy equipment operator. Most all waste coming in was acceptable at the landfill. A very small amount of unacceptable bagged kitchentype wastes, however, were spotted in a few areas, but the majority of the waste was acceptable. Please be cognizant of any wastes that are unacceptable for your Class VI landfill. The waste should be removed and properly disposed, and transporters contacted if necessary.

Thank you for your efforts in running a good landfill operation. If you have questions or need further information, please contact Matt Sullivan or Ralph Bohn at 801-538-6170.

Sincerely,

## Original Document signed by Dennis R. Downs on 10/29/08

Dennis R. Downs, Executive Secretary Utah Solid and Hazardous Waste Control Board

Enclosure: Inspection Checklist

DRD/MS/kk

c: Joseph K. Miner, M.D., M.S.P.H., Director, Utah County Health Department

Insp Rpt Oct 08 TN200800975.DOC